



# FORMAL ENFORCEMENT SUMMARY



CUPA  
Santa Barbara County Fire

8/23/2012

DATE SUBMITTED

## I. FACILITY IDENTIFICATION

BUSINESS NAME (Same as FACILITY NAME or DBA-Doing Business As)  
MC CORMIX CORPORATION

BUSINESS SITE ADDRESS  
3663 VIA REAL

BUSINESS SITE CITY 104 CARPINTERIA 93102 CA ZIP CODE 105

## VIOLATION SUMMARY

Type of Violation (check boxes that apply)

- HAZARDOUS MATERIALS 4  HAZARDOUS WASTE TREATMENT 11
- Cal-ARP REGULATED SUBSTANCES 4a  RCRA LARGE QUANTITY GENERATOR 14a
- UNDERGROUND STORAGE TANKS (USTs) 5  HOUSEHOLD HAZARDOUS WASTE 14b
- ABOVE GROUND PETROLEUM STORAGE 8  LOCAL REQUIREMENTS 15
- HAZARDOUS WASTE 9

## Narrative description of the violations observed

According to the provided information, an employee discovered an accumulation of water within the 87 and 91 UST turbine sumps. The employee chose to lift the sensors from the liquid in order to resolve the alarm condition and allow for the dispensing of fuel. The employee repositioned the sensors to a dry location on the center high-point of the USTs.

This leak detection system violation was observed by a representative of the Santa Barbara County Fire Department CUPA during an annual compliance UST inspection on March 3, 2010, (41) days after the alarm condition occurred. The Agency found the business in violation of tampering with the leak detection system.

## FORMAL ENFORCEMENT ACTION

| Type of Enforcement Action (Check one box)   | Date of Initial Enforcement Action | Date of Final Disposition | Cash Fines/Penalties Imposed | Total Costs Recovered | Value of SEP Penalties Imposed |
|--|------------------------------------|---------------------------|------------------------------|-----------------------|--------------------------------|
| <input checked="" type="checkbox"/> ADMIN <input type="checkbox"/> CIVIL <input type="checkbox"/> CRIMINAL | 5/25/10                            | 06/27/11                  | \$26,000                     | NA                    | NA                             |

## DESCRIPTION OF FINAL DISPOSITION

NARRATIVE FORMAT - (i.e. describe probation conditions, final sentencing conditions, consent order compliance schedule, etc)

Respondent operates the underground tank system in compliance with HSC, Chapter 6.7, Division 20, and California Code of Regulations, Title 23 and complies with the conditions of the permit issued by the Santa Barbara County Fire Department Certified Unified Program Agency. The Respondent shall ensure continuous proper placement and function of all UST monitoring sensors.

Respondent paid a penalty of \$26,000.00